

Mount Motor without Support
Bearing, use 3 screws only

3 pcs M4 x 10

Mount Support Bearing after belt
instalation

3 pcs M4 x 16

425mm belt



